


## *FIX W8 OEM Multitouch Capability on UnicoIII*

Eseguire al prompt comandi in administrator mode:

`bcdedit -set testsigning on`

eseguire successivamente un reboot.



```
cmd Select D:\Windows\System32\cmd.exe
D:\Windows\system32>bcdedit -set TESTSIGNING ON
The operation completed successfully.
D:\Windows\system32>bcdedit

Windows Boot Manager
-----
identifier           <bootmgr>
device               partition=C:
description          Windows Boot Manager
locale               en-US
inherit              <globalsettings>
default              <current>
resumeobject        <f4b9eab3-d8c2-11da-8bb4-d1019e73cc8d>
displayorder        <current>
toolsdisplayorder   <7af09567-c765-11da-ae0e-0014224ab5ca>
timeout              30

Windows Boot Loader
-----
identifier           <current>
device               partition=D:
path                 \Windows\system32\winload.exe
description          Microsoft Windows
locale               en-US
inherit              <bootloadersettings>
osdevice             partition=D:
systemroot           \Windows
resumeobject        <f4b9eab3-d8c2-11da-8bb4-d1019e73cc8d>
nx                   OptIn
testsigning         Yes
```